Section 1	MANA	GEMENT	OF	CHANGE (M	IOC)		ABU:	Plant:	Year
MOC		Originator:	alice in the second		assport No:	T EWO	- DI OD	Gas Recovery Plant	2010
220	11.7-540.15	Bleckinger, Meg		6/8/2010	acopon no.			19	
180000,007	2 Reviewer:	MOC Cate		PSM:		MOC Type:	Expiration Date:	Other Temporary Reason	
	, Michael R.	Routine		PHA A/C		Permanent	Expiration Date.	Caron remperary model	
	ipment Title:	1100000		re Alarm to C-1920 Tra	av 4	, ominanom			
	of Change:	ridding Lon To	riporata	1071101111110 0 1020 111	-y ·				-
		7 (Item number 1	4121	and 21.2.1.1)					
								elow 245F during stable op	erations
ease cha	nge COD tab	le to reflect the n	W IOW I	mit. This MOC must be	e past Stage	2 before 7/9/	2010.		
OC will be	e required if the	he change will:							
Cause	e the use of c	different feed, che	micals o	or catalysts?					
✓ Caus	e the use of c	different process	ondition	ns, process control, ins	trumentation	, and protecti	ve devices or affect upst	ream/downstream plants?	
Caus	e the use of r	new or modified e	quipme	nt [which is other than i	inkind]?				
Alter	equipment sit	ting, building, trail	er locat	ons, roads or fire prote	ection?				
Requ	ire modifying	existing and/or d	evelopin	g new procedures?					
ection 2							✓ Simultaneously Beg	gin Construction and Start-	ир
	277	- Table 1		Dept./Person		Date			
Stage 1	Pre-Im	plementation		Responsible		Complete	Completed By	Reference	es
•	Design Revie	ew							
	Process Eng	ineering Review		Bleckinger, Megan F	₹.	6/8/2010	Bleckinger, Megan R.		
	Instrumentat	ion Review							
Ī	Control Syste	em Review		Thomas, Lekha S.		7/6/2010	Thomas, Lekha S.		
Ī	Utilities Revi	ew							
	Environment	al/Regulatory Re	view	Tarter, Donald J.		6/24/2010	Elliott, Brad B.		
1	Safety/Regulatory Review								
Ī	Building Pen	mits Review		Linares, Elena E.		6/17/2010	Linares, Elena E.		
Ī	Mechanical I	Review							
Ī	Inspection R	eview							
Ì	Metallurgy R	eview							
Ì	Contruction	Review				7-1-1-1			
1	Leak Seal R	eview							
Ì	Relief Syster	m Review							
ı	Infrastructure	e Review							
Ì	PHA/HSE R	eview		Bleckinger, Megan F	₹.	6/9/2010	Bleckinger, Megan R.		
Authoriza	ition to Impler	ment Change (Be	gin Con	struction): Appro	ver: Seidlitz	z, Michael R.		Date: 6/29/2010	
o. T				Dept./Person		Date			
Stage 2	Pr	e-Startup		Responsible		Complete	Completed By	Reference	es
- [Procedures	Review		Henrickson, Alan C.		7/8/2010	Henrickson, Alan C.		
- 1	Communicat	tion/Training 1		Barthel, John J.		7/8/2010	Barthel, John J.		
1	Pre Start-up	Safety Review		Bleckinger, Megan F	₹.	7/8/2010	Bleckinger, Megan R.		
									3.5
Authoriza	tion to Start I	In Change:		*	0.1403	- Michael D		D-t-: 7/0/2040	
Authoriza	ation to Start-I	op Change.		Appro	iver. Seidill	z, Michael R.	· ·	Date: 7/9/2010	
Extensio	on of Tempo	rary Change	App	prover:			Expiration Date:	Extention Reason	1-1
Approve	ed By:								
_				Dept./Person		Date			
	Pos	st-Startup		Responsible		Complete	Completed By	Reference	es
	Communication/Training		porioible		- 0p.000				
Stage 3	Communica	Process Safety Information		McCall, Patrick D.		7/12/2010	McCall, Patrick D.		
		ety Information					1		
3	Process Saf	•					1	1	
3 Change i	Process Saf n Place - Rev	riews,	Appr	over:			Date:]	
Change i	Process Saf n Place - Rev	•					Date: 7/19/2010		
3 Change in	Process Saf in Place - Rev ntation & Test	riews,		over: itz, Michael R.			The state of the s		
		ety Information						•	
3 Change in Documer	Process Saf n Place - Rev	riews,	Seidl	over: itz, Michael R.			7/19/2010		

PROCESS ENGINEERING REVIEW CHECKLIST 22096 MOC Number Filing Reference You have been assigned a Process Engineering Review. This checklist is a guide to help ensure that all information Person Responsible Bleckinger, Megan R. necessary to evaluate the change is considered. Completed By Bleckinger, Megan R. Project/Equipment Title: Date Completed 6/8/2010 Adding Low Temperature Alarm to C-1920 Tray 4 DOCUMENTATION **SUMMARY OF REVIEW*** Operating data for 2005- 2Q2010 indicates no time period when 89TC245 was below 245F during ☐ Drafting Work Requisition, MFG-5545 normal operation. Data is attached in PSI. MSDS's PED Records Relief System Drawings PROCESSES REVIEW ASTM-TBP-EFV Distillation Relationships Suppliers' Performance ☐ BIN Best Practice Surface Tensions ☐ Thermal Properties Characterization of Petroleum Fractions Upstream & Downstream Impacts Composition & Flow Information □ Vapor-Liquid Equilibria □ Conversion Factor & Constants ☐ Vapor Pressures Delivery Needs Densities Viscosities ☐ Fundamental Properties Honeywell ☐ Honeywell Process Simulator ■ Material & Energy Balance

*When possible include copies of documents referenced in the summary.

Solubilities

New Catalyst of Feeds✓ Operating Parameters

Physical Properties of Streams or Catalysts

CONTROL SYSTEM REVIEW CHECKLIST

PHA A/C Record # 16927 (Item number 14.1.2.1 and 21.2.1.1)

to reflect the new low limit. This MOC must be past Stage 2 before 7/9/2010.

You have been assigned a Control System Review. This checklist is a guide to help ensure that all information necessary to evaluate the change is considered.

MOC Number	22096
Filing Reference	
Person Responsible	Thomas, Lekha S.
Completed By	Thomas, Lekha S.
Date Completed	7/6/2010

Pro	iect/	Eaui	pment	Descri	ption:

CONTROL SYSTEM:	
✓ Alarm Objective Analysis	☐ Loop Diagrams
☐ Analyzer Instruments	☐ P&ID Change due to New /
Chevmon	Modified equipment
☐ Control Objectives Analysis	 P&ID's Change - Field condition not matching existing P&ID
☐ Control Room Design	☐ Pressure Measurements
☐ Control Systems	☐ Process Alarms
☐ Control Valves	☐ Process Control
✓ DCS	Relief Systems
☐ Egatrol	☐ Shutdown Systems
☐ Electrical One-lines	System Design
☐ Field Installation	☐ Temperatue Measurements
☐ Flow Measurements	
☐ Honeywell	
☐ Honeywell Process Simulator	
\square Instrument Seals, Purges and Winterizing	
☐ Intrinsic Safety	
☐ Ladder Logic Diagrams	
Level Measurements	

SUMMARY OF REVIEW*

Add new low temperature alarm to 89TC243. The new low limit is 245 F. After reviewing process data 89TC245 is never below 245F during stable operations. Please change COD table

The COD Table currently indicates that 275F is the safe COD lower limit. If this information is no longer valid then we should make sure that the COD table gets modified as part of the MOC.

Alarm Prioritization using the Std Chevron Alarm Prioritization Matrix:

Consequence- Unstable downstream column operations and lifting of C-1950 PRD. Possible environmental impact and shutdown of all units. Calling it MAJOR because of the potential impact to shut down all units

Maximum Time to Respond- 5-30 mins

This classifies as a low priority alarm.

*When possible include copies of documents referenced in the summary.

ENVIRONMENTAL REGULATORY REVIEW CHECKLIST

You have been assigned a Regulatory Review. This checklist is a guide to help ensure that all information necessary to evaluate the change is considered.

Pro	Project/Equipment Title:				
Addi	ling Low Temperature Alarm to C-1920 Tray 4				
СН	EVRON:				
	Yellow Book				
RE	GULATORY:				
	Army Corp Permit				
	BAAQMD Air Regulations & Permits (including TitleV)				
	Bay Conservation & Development Commission (BCDC)				
	CEQA (EIR's, etc.)				
	City of Richmond Conditional Use Permits (Land use and Hazardous Materials)				
	City of Richmond Design Review Board				
	Permit to Build and Remove Wells, County Permit Required				
	Department of Transportation (DOT)				
	EPA Benzene Neshap				
	EPA Benzene Waste (BW) NESHAP				
	EPA MACT Requirements				
	EPA New Source Performance Standards (NSPS)				
	Regulation 8 Organic Compounds Rule 8 Wastewater Collection and Separation Systems				
	Risk Management & Prevention Plan (RMPP)				
П	RWQCB Waste Discharge Orders, EPA Consent Agreement Sites				
	RWQCB NPDES Regulations & Permits				
	RWQCB SB-1050, Waste Discharge Requirements (WDR)				
	Spill Prevention & Counter Measure Plan (SPCC)				
	Waste Regulations and Permits				
	Wharf-related agencies (SLC, USCG, OSPR, EPA)				
	Additions, modifications, or deletions of VOC Component/Equip				

rson Responsible:	Tarter, Donald J.
Completed By:	Elliott, Brad B.
Date Completed:	6/24/2010

SUMMARY OF REVIEW*

Per PE, change entails modifications to process - no equipment changes.

No environmental regulatory issues.

*When possible include copies of documents referenced in the summary.

BUILDING PERMITS REVIEW CHECKLIST

You have been assigned a Regulatory Review. This checklist is a guide to help ensure that all information necessary to evaluate the change is considered.

Proje	ct/Eq	Juipm	ent	Title:
-------	-------	-------	-----	--------

Adding Low	Temperature	Alarm to	C-1920	Tray 4
------------	-------------	----------	--------	--------

MOC Number	22096
Filing Reference	
Person Responsible	Linares, Elena E.
Completed By	Linares, Elena E.
Date Completed	6/17/2010

SUMMARY OF REVIEW*

MOC signed off. A City of Richmond building permit is not required based on the information provided in the scope of work, but is required for any new construction such as: electrical, instrumentation, pipe supports, structural modifications, and etc.

INSPECTION REVIEW CHECKLIST

You have been assigned a Inspection Review. This checklist is a guide to help ensure that all information necessary to evaluate the change is considered.

MOC Number: 22096

Completed On: 6/9/2010

Completed By: Bosworth, Gregory A.

Person Responsible: Bosworth, Gregory A.

Project/Equipment Description:

PHA A/C Record # 16927 (Item number 14.1.2.1 and 21.2.1.1)

Add new low temperature alarm to 89TC243. The new low limit is 245 F. After reviewing process data 89TC245 is never below 245F during stable operations. Please change COD table to reflect the new low limit. This MOC must be past Stage 2 before 7/9/2010.

Yes	No		The scope of work has been reviewed by the Chevron Fire Marshal. Scope of work does not constitute a change in fire protection.
	V	City Fire-Plan Review is Mandato	does not constitute a change in the protection.
	V	City Fire-Permit is Mandato	
	✓	City Acceptance Test is Mandato	
V		Office of Fire Prevention Review On	

HEALTH & SAFETY EVALUATION

Date Issued:		Maximo Numbe		22096
	RLOP	EWO Number		
		ery Plant 19	•	Bleckinger, Megan R.
		Seidlitz, Michael R.	•	Bleckinger, Megan R.
Project/Equip	ment Title:	Adding Low Temperature Alarm to C-1920 Tray	4 Date Completed	6/9/2010
D	escription:	PHA A/C Record # 16927 (Item number 14.1.2.	1 and 21.2.1.1)	
		Add new low temperature alarm to 89TC243. Th	e new low limit is 245 F. After reviewing process data 89TC245 is never	er below 245F during stable
Step 1:	Notify US	W ☐ USW Representation Present	USW Representative:	
Worker's Con	nmittee Men	nber/Steward's comments if unable to attend:		
	Notify Tra	iner TrainerRepresentation Present	Training Representative: John Barthel	
Step 2: In	volve: Oper	ations, Maintenance, Technical and others wit	n appropriate expertise relevant to the change (CRTC, Contractors,	etc)
Attendees:	M. Bleckinge	er, G. Carter, L. Harris, M. Demcsak, S. Brown, G. Zakre	wski	
Step 3: Th	link abaut th	se tack at hand. Discuss the existing cituation	Discuss the change. Discuss the impact of the change on the ex	isting situation. Determine the
training requi			Discuss the change. Discuss the impact of the change on the ex-	isting situation. Determine the
Step 4:	XXIII.XXIII.XXII.XXII.XXII.XXII.XXII.X		Training Type: 1	
Develop a list	of concern	s, consider your options, consider your followi	ng:	
			ng: E *Hot Work *Confined Space Entry *Evacuation Plan *Safety Operator	Proceed
*H2S *NH3 *A				Proceed Safely
*H2S *NH3 *A	Acid *Caustic	*Benzene *Fall Protection *Staging *Scott Air *PF	*Hot Work *Confined Space Entry *Evacuation Plan *Safety Operator	
*H2S *NH3 *A	Acid *Caustic	*Benzene *Fall Protection *Staging *Scott Air *PF	*Hot Work *Confined Space Entry *Evacuation Plan *Safety Operator	
*H2S *NH3 *A	Acid *Caustic	*Benzene *Fall Protection *Staging *Scott Air *PF	*Hot Work *Confined Space Entry *Evacuation Plan *Safety Operator	
*H2S *NH3 *A	Acid *Caustic	*Benzene *Fall Protection *Staging *Scott Air *PF	*Hot Work *Confined Space Entry *Evacuation Plan *Safety Operator	
*H2S *NH3 *A	Acid *Caustic	*Benzene *Fall Protection *Staging *Scott Air *PF	*Hot Work *Confined Space Entry *Evacuation Plan *Safety Operator	
*H2S *NH3 *A	Acid *Caustic	*Benzene *Fall Protection *Staging *Scott Air *PF	*Hot Work *Confined Space Entry *Evacuation Plan *Safety Operator	
*H2S *NH3 *A	Acid *Caustic	*Benzene *Fall Protection *Staging *Scott Air *PF	*Hot Work *Confined Space Entry *Evacuation Plan *Safety Operator	
*H2S *NH3 *A	Acid *Caustic	*Benzene *Fall Protection *Staging *Scott Air *PF	*Hot Work *Confined Space Entry *Evacuation Plan *Safety Operator	
*H2S *NH3 *A	Acid *Caustic	*Benzene *Fall Protection *Staging *Scott Air *PF	*Hot Work *Confined Space Entry *Evacuation Plan *Safety Operator	
*H2S *NH3 *A	Acid *Caustic	*Benzene *Fall Protection *Staging *Scott Air *PF	*Hot Work *Confined Space Entry *Evacuation Plan *Safety Operator	
*H2S *NH3 *A	Acid *Caustic Concern	*Benzene *Fall Protection *Staging *Scott Air *PF	*Hot Work *Confined Space Entry *Evacuation Plan *Safety Operator	
*H2S *NH3 *A	Acid *Caustic Concern ems	*Benzene *Fall Protection *Staging *Scott Air *PF Consequence	*Hot Work *Confined Space Entry *Evacuation Plan *Safety Operator Mitigation	
*H2S *NH3 *A	Acid *Caustic Concern ems	*Benzene *Fall Protection *Staging *Scott Air *PF	*Hot Work *Confined Space Entry *Evacuation Plan *Safety Operator Mitigation	

Page 1 of 1

PROCEDURE REVIEW CHECKLIST

You have been assigned a Procedure Review. This checklist is a guide to help ensure that all information necessary to evaluate the change is considered.

PHA A/C Record # 16927 (Item number 14.1.2.1 and 21.2.1.1)

MOC Number	22096	
Filing Reference		
Person Responsible	Henrickson, Alan C.	
	Henrickson, Alan C.	
Date Completed	7/8/2010	

Project/Equipment Description:

Add new low temperature alarm to 89TC243. The new low limit is 245 F. After reviewing pate to reflect the new low limit. This MOC must be past Stage 2 before 7/9/2010.	process data 89TC245 is never below 245F during stable operations. Please change COD table
☐ Alarm Procedures	SUMMARY OF REVIEW*
☐ Any Special or unique hazards	Added new lower safe limit to Vol#1 COD Table Pg. 10
☐ COD/Ops Monitor	
✓ Consequences of deviation	
Control measure to be taken if physical contact or airborne exposure occurs.	
Precautions necessay to prevent exposure, including administrative controls, engineering controls, and personnel protective equipment.	
properties of, and hazards presented by, the chemicals and operation of the process.	
\square References to additional procedures, such as Safe Work Practices	
☐ Routine Duties	
☐ Safety system and their functions	
☐ Steps required to correct and/or avoid deviation	
Steps fo each operatong Phase	
☐ Emergency	
☐ Normal	
☐ Start-Up/Shutdown	
☐ Temporary	

SUMMARY OF REVIEW*

*When possible include copies of documents referenced in the summary.

Stage Two Training and Communication Review

1/29/2013 10:06:14 AM

	MOC No:	22096
✓ Identify the affected employees. * Maintenance and Technical affected?	Date Completed:	7/8/2010
 Employee who will require training to start up the change based on the level of training. 	Completed By:	Barthel, John J.
* Employees who will receive training after the start up BUT	Person Responsible:	Barthel, John J.
before they can perform work affected by the change	Project/Equipm	ent Title:
Procedures have been modified/written (Ops/SSO/Trainer)	Adding Low Temp	perature Alarm to C-1920 Tray 4
✓ Identify the affected employees		
 Lesson plan cover sheet (includes training objective statement and list of affected employees) 	Summary of Re	eview:
 * Procedural changes (Standing Orders, mark-ups) * Flow daigrams (final or mark-ups) 	The second control of	mperature alarm to 89TC243. The new low limit iewing process data 89TC245 is never below
✓ Determine level of training	245F during stable the new low limit.	e operations. Please change COD table to reflect
Training has been scheduled		
Affected employees have been trained in order to start up the change.	All affected emplo	yees have been trained via e-mail.

APPENDIX III PRE-START-UP SAFETY REVIEW CHECKLIST

You have been assigned a Pre Start-Up Safety Review. This checklist is a guide to help ensure that all information necessary to evaluate the change is considered.

assport No:		MOC Number	22096	
EWO No.:		Filing Reference		
MOC PSSR.:	22096.001	Person Responsible	Bleckinger, Megan R.	
100 1 00IV		Completed By	Bleckinger, Megan R.	
		Date Completed	7/8/2010	

Project/Equipment Description:

Adding Low Temperature Alarm to C-1920 Tray 4			

Subsystem:

Subs,	ystem.		
NOT	The PSSR facilitator shall involve employees with expertise in process operations, maintenance, and enginee the process system being evaluated.	ering, based upon their experience	e and understanding o
The	e following requirements for PSSR shall be addressed:	Approved by:	Date
	Has the equipment and construction been completed in accordance with the critical design specifications? Some examples of how this may be accomplished are: Review of equipment quality assurance and inspection records. Review of construction inspection records. P & ID "check" after mechanical completion, and facility "walk-through" inspection.	Bleckinger, Megan R.	7/7/2010
	Justification: Yes		
*	Are Safety, operating, manintenance, and emergency procedures in place and adequate? The phrase "in place and adequate" means: written, reviewed, approved, and accessible to employees requiring the procedures in their work. This does not prevent the use of "mark-up" procedures to satisfy the requirement, but these must undergo the same review and approval and training interaction as would "the final version" of the same procedure and would require rigorous control.	Bleckinger, Megan R.	7/8/2010
	Justification: COD Table updated		
3. I	Has the communication or training of affected operating, maintenance, or contract workers been completed? * Maintenace employees, contractors, and other employees whose work is affected by the change must be informed of the change and training in the impact on their job tasks before the changed equipment is started up.	Bleckinger, Megan R.	7/8/2010
	Justification: J. Barthel completed		
3	Have the quality assurance goals of mechanical integrity been met? * Ensure that changes are suitable for the intended service. * Ensure that the quality of the work is acceptable. * Ensure that the quality of the Leak Seal is acceptable.	Bleckinger, Megan R.	7/7/2010
	Justification: N/A		
5. I	Have all recommendations resulting from PHA's or HSE's been addressed of resolved	Bleckinger, Megan R.	7/7/2010

*When possible include copies of documents referenced in the summary.

* Ensure tall Recommendations have been documented as addressed or resolved

Page 1 of 2

APPENDIX III MOC Number 22096 Passport No: PRE-START-UP SAFETY REVIEW CHECKLIST Filing Reference EWO No .: Person Responsible Bleckinger, Megan R. You have been assigned a Pre Start-Up Safety Review. This MOC PSSR.: 22096.001 checklist is a guide to help ensure that all information Completed By Bleckinger, Megan R. necessary to evaluate the change is considered. Date Completed 7/8/2010 Project/Equipment Description: Adding Low Temperature Alarm to C-1920 Tray 4 Subsystem: Justification: This is a PHA A/C Are there any safety-related exceptions encountered during the PSSR that require follow-up after started up? Miscellaneous Comments: Completed Completed

Owner

By

On

Notified

Exception

					Filing Reference	MaCall Datrials D
					Person Responsible	
	T141					McCall, Patrick D.
roject/Equipment	t/Equipment Title: Date Completed			7/12/2010		
PSI Documents Typ	Numbe	Owne	Markup Date	Final Date	Document UR	
		· [Brows \\\ric841vmg3web1\\	osidocs\$\2 Open

SUMMARY OF REVIEW*

No PSI.

*When possible include copies of documents referenced in the summary.

Tuesday, January 29, 2013

Page 1 of 1